Importing Horizontal and Vertical Alignments Using SDMS (into GEOPAK)

1. Once you have activated Project Manager inside of GEOPAK, click on the COGO (Coordinate Geometry) icon.



2. Confirm your Project Name, Job Number, and Operator Code, then click on the *OK* button.

GEOPAK Coordinate Geometry			
Project Name Job Number Operator Code	Itest 101 Select		
Subject			
ок Д	Cancel		

3. In the Coordinate Geometry dialog box, click on *<u>File</u>*, then *<u>Import</u>*, then *<u>SDMS</u> <i>Alignments and Points*.

Coordinate Geometry Job: 101 Operator: tt				
<u>File E</u> dit	E <u>l</u> ement <u>V</u> iew <u>T</u> ools <u>U</u> ser			
Append Catalog Delete Load Output Print Restore Save	ization ▼ OFF (Feature) ▼ Browse			
<u>E</u> xport	•			
<u>I</u> mport	▶ <u>R</u> DS			
E <u>x</u> it	SDMS Alignments and Points			

4. In the Import SDMS Alignments and Points dialog set the *Input* to either *Horizontal Alignments* or *Vertical Alignments*, then click on the *Select* button.

8 Import SDMS Alignments and Points	×	8 Import SDMS Alignments and Points	×
SDMS File	Select	SDMS File	Select
Input Horizontal Alignments 💌		Input Vertical Alignments 💌	

5. The dialog box below will appear to allow you to navigate to the folder where you stored your IGrds exported data. This example shows an exported profile file. If you had set your Input choice to *Horizontal Alignments* (as shown above left) your selection choices would have an ".ali" extension. Click on the file that you want to import, then click on the *OK* button.

SDMS Input File		
F <u>i</u> les:	Directories:	
A.pro	c:\igmod1\	
A.pro	igmod1 Im Dtm Im sample	Leip
List Files of <u>T</u> ype:	Dri <u>v</u> es:	
^.pro	IC:	

6. The file you choose will appear in the blank field to the right of *SDMS File*. Confirm the file name, then click on the *Apply* button.

8 Import SDMS Alignments and Points				
SDMS File	c:\igmod1\A.pro	Select		
Input	Vertical Alignments 🔹			

The Vertical or Horizontal Alignment will then be imported onto COGO. If there are no errors you will see and Information dialog that states that your alignment was imported successfully. If you have errors, then contact the AES Helpdesk @ 1-(888)683-0345 or (804)786-1280.

<mark>ट</mark> िव <u>F</u> ile	oordinate <u>E</u> dit E <u>l</u> er	Geomet nent <u>V</u> ie	rry Job: 101 w <u>T</u> ools <u>U</u> ser	Operator: tt	<u> </u>
Dis	able Visual	T	💭 🕂 🏹	(F) (⁰) ([−]) (¹) (¹ →224 (¹)) (¹ →2 [−]) (²) (² → [−]) (² →	Edefine
_ <u>C</u> OG	i0 Key-in	END PRO) 101-A		
<*	6	VPI	3 S 20+15.	000 E 761.187 L 105.000000000	E E
<*	7	VPI	8 Import SD	MS Alignments and Points	
<*	8	VPI	SDMS File	c:\igmod1\A.pro	
10	Vertical Alignment File imported successfully.				

8. You may review your data in COGO. If everything looks OK, then exit COGO. You will be asked to save your session, which you should do by clicking on the Yes button. This will save your input data, which can and will serve as a backup of your alignment data.



9. Key in an appropriate name in the *Save As* field, then key in a description of that alignment in the *Subject* field. When you are done click on the *OK* button. This file will be saved to your GEOPAK project directory on the server.

Save		
Save As Files	ml	Subject mainline profile from IG
Name	Subject	
1		
		Cancel